7*	Approved For Release 2004/04/13 : CIA-RDP82-00457F	R003300080002-2	ho
•	CLASSIFICATION		25X1 7乙
	CENTRAL INTELLIGENCE AGENCY 25X1	REPORT	
	INFORMATION REPORT	CD NO.	
COUNTRY	on k	DATE DISTR.	15 September 38
SUBJECT	of Porce epair and Tost Thank of Krausogersk, tear account	NO. OF PAGES	2
PLACE ACQUIRED	25X1	NO. OF ENCLS.	1
DATE OF IN		SUPPLEMENT TO	)
	25X1	REPORT NO.	
This decreased of the business of the business of the coefficient business of the business of	This	LUATED INFORMAT	
25X1	Direc Archiv	document is hereby FIDENTIAL in accord of 16 October 10 for of Central Intellig vist of the United St	73 from w
1.	Locati- a	Review Date: 2008	ates.
	Immediately south of the MOSCOW - RIGARR I miles west of the KRASMOGORSK AR station (350 m). "est of the plant the above RR line	57°32'E/55°49	\$ <sup>2</sup>
	Plant Installations		•
	See attache i sketch and legend.		
3.	Plant History		
	The plant was an air force workshop supprofunce colonel. Its oldest section (motor shop) way be 15 years old. Other workshop later; one large shop was still under consofticers and EM of the SovietAir Force were plant as supervisors. Orkers, and guards.	vehicle repail s had been bu truction. Ma	r 11: ny
<b>&amp;</b> o	Wirk Force		
	Three hundred Soviets working one shift we building F (see attached sketch) in additi	re quartered on to one hun	<u>tù</u> dred
5.	<u>Production</u>		
	a. Jot-fighter turbines, duplicates of Ge German FWS (skilled workers) were not assi production but only to the construction of CLASSIFICATION (SM)	enec to mass	<b>V</b>
STATE	MAYY & NSRB DISTRIBUTION		
ARMY #	S AIR # S FBI		

b. A radar set of US origin was set up in the factory yard. Height of the set, 40 to 50 feet. A loop antenna in the shape of a round screen (about 13 feet diameter) was mounted on its top. At its bottom there was a switch desk with switch panels. At the desk there was a board on which colored signs flared up from time to time.

- c. Aircraft radio sets were being built in the radio shop.
- d. Motor vehicle repair was being performed; the recuired spare parts were produced in their own workshops.

## 6. Security Measures

The plant was operated by the Soviet Air Force and guarded by air force soldiers. It was surrounded by a feace.

## 25X1 Comment:

- a. The above plant is the previously reported repair and test plant located between PAYSHIMO and KMASTOGORSK. According to available information, the plant, designated MEB (Novaya Eksperimentalnaya Baza), was a Soviet in Force plant.
- b. The above data confirmed previous information, supplementing it with the statement that individual turbo-jet powerplant models were being produced.
- c. The radar set (para. 5b) seems to have been a position finder set similar to the German "verzburg Riese".

25X1		

	25X1		
CORECREE			